Members Tests Timings (Gate Closure Time- 15:00)

	Production	Testing	
Pre-Coupling	09:00	13:00	Start of the Market Coupling Session
	09:15	**13:15**	**Latest Time to start an IC for issues in the Configuration Synchronization step**
	09:45	13:20	Deadline to skip the Configuration Synchronization step
	10:30	13:30	Target Time for submission of the Network Data in the PMB
	11:00	**14:00**	**Latest time to start an IC for Network Data missing in PMB (TSOs can join the call)**
	11:15	14:15	Risk of Partial Decoupling for one or more interconnectors (at regional level)
	11:30	14:30	**Deadline to declare Partial Decoupling for an interconnector** (at regional level)
Coupling	12:00	15:00	PX OBK Gate Closure Time
	12:10	15:10	PMB GCT // Reception of all OBK in PMBs → Start of Calculation
	12:25	**15:25**	**Latest Time to start an IC for OBK related reasons (TSOs can join the call 5 mins later)**
	12:40	15:40	Deadline to send the message for Risk of Partial Decoupling to the TSOs/market
	12:27	15:27	End of Calculation
	12:29	15:29	Reception of Results in all PX Systems + Start of 12 min Confirmation process
	12:41	15:41	Deadline to send the Preliminary Confirmations → Generation of GPC
	13:05	**16:05**	**Deadline to declare Partial Decoupling**
	12:45	**15:45**	**Publication of Preliminary Results and sending to the TSOs →** Start of 10 min Final Confirmation process
	12:57	15:57	Deadline to send the Final Confirmations
	12:57	15:57	Reception of all Final Confirmations in the PMB → Sending of GFC
	12:57	15:57	Reception of Global Final Confirmation in the Local PMBs
	12:58	**15:58**	**Publication of Final Results →** Start of Notification Process
	13:15	**16:15**	**Latest time to Start an IC and invite TSOs**
	13:50	16:50	Deadline to send the message for Risk of Full Decoupling to the TSOs/market
	14:20	**17:20**	**Deadline to declare Full Decoupling**